

LICENCE PLATE, PROP ROD, VACUUM CONNECTOR ASSORTMENTS

LICENCE PLATE HARDWARE



NEW!

FMSI #0433
GM - FORD
CHRYSLER - HONDA
TOYOTA - MAZDA
LICENCE PLATE
BOLTS, SCREWS,
NUTS & NYLON
HARDWARE
146 pieces

DOMESTIC & IMPORT HOOD PROP ROD RETAINER ASSORTMENT



FMSI #0381
GM - FORD
CHRYSLER
HONDA - TOYOTA
SATURN - ISUZU,
PROP ROD CLIPS

41 pieces

VACUUM CONNECTOR ASSORTMENT



FMSI #0282
VACUUM CAPS,
UNIONS, TEES,
Y & F CONNec-
TORS

107 pieces

PLASTIC ASSORTMENT BOXES



NEW!
6-12-18-24 hole
removable dividers

FMSI #0066

6-1/2" deep
10-1/2" wide
1-1/2" high



FMSI #0070

9-1/2" deep
14" wide
6" high



TRIM PANEL CLIPS

FMSI #0368
180 piece
Assortment



SOLDERLESS TERMINALS

FMSI #0352
240 piece
Assortment



HEAT SHRINK TERMINALS

FMSI #0382
136 piece
Assortment

100% SILICONE BRAKE LUBE

FMSI #49592



- Original equipment style brake and multi-purpose lubricant
- Stops caliper slides from seizing
- Non petroleum based, can be used for caliper seals
- Will not wash off

100% SILICONE DIELECTRIC COMPOUND

FMSI #49593



- Original equipment style dielectric compound
- Stops arcing on electrical components
- Stops spark plug wire terminals from seizing to spark plugs
- Excellent for metal to metal contact points
- Will not wash off

HEADLIGHT BULB SOCKETS



FMSI#	DESCRIPTION
3570	Halogen bulb socket for 9004 & 9007 bulbs
3571	Halogen bulb socket for 9005 bulb
3572	Halogen bulb socket for 9006 bulb

GENERAL MOTORS W/BODY REAR LEAF SPRING FRICTION BLOCK

FMSI #2650



Application

1988 - 95 W/Body Chevrolet Lumina, Pontiac Grand Prix, Oldsmobile Cutlass, and Buick Regal. Replaces original equipment bushing on cross mounted leaf spring ends. Eliminates costly replacement of complete leaf spring. Easily installed in under 30 minutes.

GM 3800 (K) INTAKE AND PLENUM REPAIR KIT



O.E. Plenum in need of repair
(Use plenum sleeve)



New EGR Port Adapter from FMSI Kit #4250 installed in intake. Smaller diameter adapter allows air flow to cool and eliminate breakdown of plastic plenum.

FMSI #4250



Plenum Sleeve

EGR Port Adapter installed (flange side down into intake)

SILICONE LUBE, BULB SOCKETS, PLENUM REPAIR